




Overview: Part of spill impact on 20'' Kolocreek – Rumuekpe Pipeline at Odau-KP19 Outside the Right of Way . Picture was taken during Joint Investigation of 14th December 2019.



Close-up: Illegal Fitting on 20'' Kolocreek – Rumuekpe Pipeline at Odau-KP19. Picture was taken during Joint Investigation of 14th December 2019