



**Overview:** Part of spill impact on 12" Imo River2 Pipeline Right of Way at Umuololo Picture was taken during Joint Investigation of 18<sup>th</sup> December 2019.



**Close-up:** Illegal fitting on 12" Imo River2 Pipeline at Umuololo . Picture was taken during Joint Investigation of 18<sup>th</sup> December 2019.