



Overview: Part of spill impact on 8" Nkali - Imo River 2 Pipeline Right of Way at Odagwa
 Picture was taken during Joint Investigation of 28th December 2019.



Close-up: Plugged Drilled Hole on 8" Nkali - Imo River 2 Pipeline at Odagwa . Picture was taken during Joint Investigation of 28th December 2019.