




Overview: Part of spill impact on 20 " Kolocreek – Rumuekpe Pipeline Right of Way at Okporowo Picture was taken during Joint Investigation of 21st December2019.



Close-up: Plugged Illegal Fitting on 20 " Kolocreek – Rumuekpe Pipeline at Okporowo. Picture was taken during Joint Investigation of 21st December2019