



Overview: Part of spill impact on 18" Assa - Rumuekpe Pipeline Right of Way at Assa. Picture was taken during Joint Investigation of 19th December 2019.



Close-up: Plugged illegal fittings on 18" Assa - Rumuekpe Pipeline at Assa. Picture was taken during Joint Investigation of 20th December 2019.