




**Overview:** Part of spill impact on 6'' Tunu 3T Flowline at Egbemo Angalabiri Agbidiama. Picture was taken during Joint Investigation of 30<sup>th</sup> January 2020.



**Close-up:** Hacksaw Cut on 6'' Tunu 3T Flowline at Egbemo Angalabiri Agbidiama. Picture was taken during Joint Investigation of 30<sup>th</sup> January 2020.