




Overview: Part of spill impact on 14" Okordia - Rumuekpe Pipeline Right of Way at Ikarama. Picture was taken during Joint Investigation of 15th July 2019.



Close-up: Illegal fitting on 14" Okordia - Rumuekpe Pipeline at Ikarama. Picture was taken during Joint Investigation of 15th July 2019.