



Overview: Part of spill impact on 20'' Kolocreek - Rumuekpe Pipeline Right of Way at Odau-km19. Picture was taken during Joint Investigation of 22<sup>nd</sup> July 2019.



Close-up: Illegal fitting on 20'' Kolocreek - Rumuekpe Pipeline at Odau-km19. Picture was taken during Joint Investigation of 22<sup>nd</sup> July 2019.