




**Overview:** Part of spill impact on 12" Imo River – Ogale Pipeline Right of Way at Ogale. Picture was taken during Joint Investigation of 11<sup>th</sup> July 2019.



**Close-up:** Plugged Illegal Fitting on 12" Imo River – Ogale Pipeline Right of Way at Ogale. Picture was taken during Joint Investigation of 11<sup>th</sup> July 2019