


Overview: Part of spill impact on 18" Assa - Rumuekpe Pipeline Right of Way at Egbeda. Picture was taken during Joint Investigation of 22nd July 2019.



Close-up: Hawksaw Cut on 18" Assa - Rumuekpe Pipeline Egbeda. Picture was taken during Joint Investigation of 22nd July 2019