



**Overview:** Part of spill impact on 14" Okordia - Rumuekpe Pipeline Right of Way at Ula-Ikata. Picture was taken during Joint Investigation of 4<sup>th</sup> July 2019.



**Close-up:** Drilled Hole on 14" Okordia - Rumuekpe Pipeline at Ula-Ikata. Picture was taken during Joint Investigation of 3<sup>rd</sup> July 2019



Close-up: Drilled Hole on 14" Okordia-Rumuekpe Pipeline at Ula-Ikata. Picture was taken during Joint Investigation of 3<sup>rd</sup> July 2019



Close-up: Drilled Hole on 14" Okordia - Rumuekpe Pipeline at Ula-Ikata. Picture was taken during Joint Investigation of 3<sup>rd</sup> July 2019