

# JOINT INVESTIGATION REPORT

INCIDENT NO: 2365292 JIV report S/N: 1030009

(Note: As practicable as possible the JIV report is to be signed in the field by all the participating parties)

## A. GENERAL INFORMATION:

1. Fountain Incident Number: 2365292 2. Type of incident\* OIL SPILL  
3. Name of Location 36" NKPOKU - OGALE PIPELINE  
4. Name of nearest community RUMUESARA 5. State: RIVERS 6. LGA OBIO-AKPO  
7. Type of Production facility/Installation OIL PIPELINE  
8. Asset owner/District THE SHELL PETROLEUM DEVELOPMENT COMPANY OF NIGERIA LIMITED / PIPELINE

## B. INCIDENT INFORMATION:

9. Details of incident  
a. Date Reported: 2<sup>ND</sup> JUNE, 2019  
b. Start date/time of investigation: 5<sup>TH</sup> JUNE, 2019 / 10:04 HRS  
c. Investigation End date: 5<sup>TH</sup> JUNE 2019 Actual investigation duration, days: ONE (1) DAY  
d. Description of spill point environment  
 Firm soil  Loose soil  Recently excavated area  
 Under water  Swampy  Exposed pipe surface  
 Well Platform (on Water)  Drill Rig

Additional observations around the spill point: SANDBAGS CONCEALING CRUDE OIL THEFT POINT WAS OBSERVED BY THE JOINT INVESTIGATION TEAM.

## e. Description of leak point (tick as applicable);

- |  |   |  |
|--|---|--|
| <input type="checkbox"/> Drilled hole  | <input type="checkbox"/> Hack saw cut         | <input type="checkbox"/> Tear (_____)                                      |
| <input type="checkbox"/> Complete Rupture                                      | <input type="checkbox"/> Inward dent,         | <input type="checkbox"/> Well head tampering                               |
| <input checked="" type="checkbox"/> Failed Weld on illegal hot tap valve       | <input type="checkbox"/> Failed Clamp,        | <input type="checkbox"/> Missing Pipeline/Flowline                         |
| <input checked="" type="checkbox"/> Crude oil theft (illegal bunkering) point, | <input type="checkbox"/> Saver-pit over flow  | <input type="checkbox"/> Third party tampering with Clamp                  |
| <input type="checkbox"/> Third party tampering with valve setting              | <input type="checkbox"/> Bulging Outward      | <input type="checkbox"/> Third party tampering with flange,                |
| <input type="checkbox"/> Flare System/Bund wall failure                        | <input type="checkbox"/> Cold vent            | <input type="checkbox"/> Surge vessel overflow,                            |
| <input type="checkbox"/> Valve Failure   | <input type="checkbox"/> Relief valve failure | <input type="checkbox"/> Accidental 3 <sup>rd</sup> party equipment impact |
| <input type="checkbox"/> Others(specify) _____                                 |   |  |

## f. Incident caused by:

- Third party interference (Sabotage ; crude theft ; Line theft ; Accidental 3<sup>rd</sup> party damage   
 Operational  Others (including Mystery spills) \_\_\_\_\_

\*This can be: a) Oil Spill b) Drilling fluid/Chemical c) Siltation d) construction e) Encroachment f) Fire, g) non leaking Theft point removal  
Version: 2019/01  
Distribution of copies : White (Asset Owner); Pink (DPR); Green (NOSDRA); Yellow (State Ministry of Environment); Blue (Host Community)

# JOINT INVESTIGATION REPORT

INCIDENT NO: 2365292 JIV report S/N: 1030039

g. Spill point coordinates (THEFT POINT)

h. Measuring unit

WGS 84

Northing:	Easting:
4.91995	7.03374
/	/
/	/

## C. RISK ASSESSMENT

10. Type of environment:

Land     
  Swamp     
  Water     
  Seasonal swamp     
  Shoreline/Waterfront

i. Type of environment to which oil has spread:

Land     
  Swamp     
  Water     
  River (identify) \_\_\_\_\_

ii. Weather condition:

Rain     
  Sunny     
  Dry     
  Wet     
  Windy     
  Hot     
  Cool

11. Distance to Sensitive habitat within 100m radius

<input type="checkbox"/> Government reserved and designated protected area	[ Nil ,m]
<input type="checkbox"/> Drinking water source	[ Nil ,m]
<input checked="" type="checkbox"/> Built up area	[ 20 ,m]
<input type="checkbox"/> Farmlands	[ Nil ,m]
<input type="checkbox"/> Fish Farm/Pond	[ Nil ,m]
<input type="checkbox"/> Fishing net	[ Nil ,m]
<input type="checkbox"/> Others (specify):	[ Nil ,m]

12. Containment measures put in place;

Booms     
  Trench     
  Dyke     
  Natural depression     
  Pit     
  None  
 Others: \_\_\_\_\_

13. Any pictures or video coverage?       [N]

14. Further response/repair initiated as at the time of JIV?       [N]

If yes to item 14, give brief description:

RECOVERY AND REPAIR WORK ACTIVITIES ONGOING

15. Was there any disruption to the investigation?

# JOINT INVESTIGATION REPORT

INCIDENT NO: 2365292 JIV report S/N: 1030009

If yes to item 15 give brief description:

NOT APPLICABLE

16. Was JIV delayed? [Y] NT

If yes to item 16 give brief description: NOT APPLICABLE

**D. TYPE/NUMBERS OF PROPERTIES, IF ANY, FOUND WITHIN THE AREA OF SPREAD OF OIL**

17. Structures / Properties

S/N	Type of Structures	Description	Size	Number	Comments
<u>NONE WITHIN AREA OF IMPACT</u>					

18. Crops/Economic Trees

S/N	Type of crops	Young	Medium	Matured	Quantity	Comments
<u>NONE WITHIN AREA OF IMPACT</u>						

19. Fish/Nets/Ponds


S/N	Fish/Nets/Ponds	Description	Quantity/Size	Comments
<u>NONE WITHIN AREA OF IMPACT</u>				

20. Others (Specify) i.e. Animal Traps

S/N	Others	Description	Quantity/Size	Comments
<u>NONE WITHIN AREA OF IMPACT</u>				

**E. GRAPHIC DESCRIPTION OF LEAK POINT** (while detail report of the leak point should be contained in the leak report, overview sketch of the site should be added as an appendix 1)

SECTION OF 36" NKPOKU - OGALE PIPELINE AT RUMUESHARA (ENKRA) SHOWING CRUDE OIL THEFT POINT AT 12 O'CLOCK POSITION.



FROM NKPOKU TO OGALE

Version 2019/01



# JOINT INVESTIGATION REPORT

INCIDENT NO: 2365292 JIV report S/N: 1030009

## G. INCIDENT INFORMATION:

### a. Impacted Area Details

- Total calculated area of impact 0.062ha
- Impact within SPDC R.O.W. YES
- Impact outside SPDC R.O.W. YES

### b. Volume of oil recovered before completion of JIV ( $V_{rec}$ ):

Recovered oil $V_{rec}$ :	<u>5</u>	Barrels
---------------------------	----------	---------

Controlled recovery/evacuation from source with no impact to environment:

<u>NIL</u>	Barrels
------------	---------

### c. Net Estimated Spilled Volume $V_{Est}$ (bbls)\* =

6.98 BARRELS


### Estimated Reported Volume\*\* $V_{rep}$ (bbls) =

7 BARRELS

#### \*Notes:

- Volume estimation was done using an excel based tool. (see attached for details on the calculation)
- Reported spilled volume is an estimate

Write other relevant notes taken into consideration for volume estimation or cause of spill:



Calculation of the respective estimated volume is to be done on site as far as practicable using the new spill volume estimation software on site; Conversion of  $m^3$  to barrels is Volume ( $m^3$ )  $\times$  6.29; \*\*Round up estimated volume to next whole number using the following rules:

- Any spill volume in excess of 1 bbl is rounded up to the next whole number.
- Any spill volume in less than 1 bbl is rounded up to the next 0.1 bbl.

Examples: Calculated volume = 15.3 bbl — Reported volume = 16 bbl  
Calculated volume = 0.35 bbl — Reported volume = 0.4 bbl  
Calculated volume = 0.01 bbl — Reported volume = 0.1 bbl.

Wherever this estimation tool is not applicable please refer to paragraph 6c (Deviations) of the JIV procedure to use appropriate steps for column estimation; record the calculation in a plain sheet of paper and attach to the JIV report.


Version 2019/01

Distribution of copies: White (Asset Owner); Pink (DPR); Green (NOSDRA); Yellow (State Ministry of Environment); Blue (Host Community).  
Page 5 of 8

# JOINT INVESTIGATION REPORT

INCIDENT NO: 2365292 JIV report S/N: 1030009

f. Appendix I: Overview sketch of the site



Version 2019/01

Distribution of copies: White (Asset Owner); Pink (DPR); Green (NOSDRA); Yellow (State Ministry of Environment); Blue (Host Community)

# JOINT INVESTIGATION REPORT

INCIDENT NO: 2365292 JIV report S/N: 1030009

## d. General Status of the site

i. Joint investigation of the incident site found that there is no residual impact after the initial response and JIT therefore recommend that the site be closed out <input type="checkbox"/>
ii. Investigation of the incident site showed that there is residual impact on site requiring further works <input checked="" type="checkbox"/>

## e. Representatives

<p>This report was <u>filled, agreed and signed</u> by the following joint investigation team representatives:</p> <ul style="list-style-type: none"><li>• Host Community: <input checked="" type="checkbox"/></li><li>• Department of Petroleum Resources [DPR]: <input checked="" type="checkbox"/></li><li>• National Oil Spill Detection and Response Agency [NOSDRA]: <input checked="" type="checkbox"/></li><li>• State Ministry of Environment [SME]: <input checked="" type="checkbox"/></li><li>• Shell Petroleum Development Company [SPDC]: <input checked="" type="checkbox"/></li><li>• <i>Separate DPR form has been filled out with same findings</i>: <input checked="" type="checkbox"/></li></ul> <p style="text-align: right;"><i>Tick as applicable</i></p>
--