




Overview: Part of spill impact on 36'' Nkpoku – Ogale Pipeline Right of Way at Rumuesara-Eneka. Picture was taken during Joint Investigation of 5th June 2019.



Close-up: Plugged Illegal Fitting on 36'' Nkpoku – Ogale Pipeline at Rumuesara-Eneka. Picture was taken during Joint Investigation of 5th June 2019.