



**Overview:** Part of spill impact on 12" Imo River – Ogale Pipeline Right of Way at Uzuaku. Picture was taken during Joint Investigation of 6<sup>th</sup> June 2019.



**Close-up:** Illegal fitting on 12" Imo River – Ogale Pipeline at Uzuaku. Picture was taken during Joint Investigation of 6<sup>th</sup> June 2019