


Overview: Part of spill impact on 18" Assa – Rumuekpe Pipeline Right of Way at Egbeda
 Picture was taken during Joint Investigation of 5th June 2019.



Close-up: Leaking Illegal fitting on 18" Assa – Rumuekpe Pipeline at Egbeda. Picture was taken during Joint Investigation of 5th June 2019