




Overview: Part of spill impact on 8" Nkali – Imo River2 Pipeline Right of Way at Odagwa. Picture was taken during Joint Investigation of 6th June 2019.



Close-up: Leaking Illegal Fitting on 8" Nkali – Imo River2 Pipeline at Odagwa. Picture was taken during Joint Investigation of 6th June 2019