



**Overview:** Part of spill impact on 24" Ogale – Bomu Pipeline Right of Way at Agbeta. Picture was taken during Joint Investigation of 21<sup>st</sup> June 2019.



**Close-up:** Illegal Fitting on 24" Ogale – Bomu Pipeline at Agbeta. Picture was taken during Joint Investigation of 21<sup>st</sup> June 2019.