




Overview: Part of spill impact on 18" Assa – Rumuekpe Pipeline Right of Way at Awarra. Picture was taken during Joint Investigation of 13th June 2019.



Close-up: Plugged Illegal fitting on 18" Assa – Rumuekpe Pipeline at Awarra. Picture was taken during Joint Investigation of 13th June 2019