




Overview: Part of spill impact on 14" Okordia-Rumuekpe Pipeline Right of Way at Akara-Olu. Picture was taken during Joint Investigation of 11th June 2019.



Close-up: Illegal fitting on 14" Okordia-Rumuekpe Pipeline at U Akara-Olu. Picture was taken during Joint Investigation of 11th June 2019.