


Overview: Part of spill impact on 14" Okordia - Rumuekpe Pipeline Right of Way at Akara - Olu. Picture was taken during Joint Investigation of 14th June 2019.



Close-up: Illegal fitting on 14" Okordia - Rumuekpe Pipeline at Akara - Olu. Picture was taken during Joint Investigation of 14th June 2019.