


Overview: Part of spill impact on 14" Okordia – Rumuekpe Pipeline Right of Way at Oshika. Picture was taken during Joint Investigation of 7th June 2019.



Close-up: Plugged Illegal fitting on 14" Okordia – Rumuekpe Pipeline at Oshika. Picture was taken during Joint Investigation of 7th June 2019