


**Overview:** Part of spill impact on 14" Okordia - Rumuekpe Pipeline Right of Way at Akara-Olu. Picture was taken during Joint Investigation of 10<sup>th</sup> June 2019.



**Close-up:** Illegal fitting on 14" Okordia - Rumuekpe Pipeline at Akara-Olu. Picture was taken during Joint Investigation of 10<sup>th</sup> June 2019.