


Overview: Part of spill impact on 14" Okordia-Rumuekpe Pipeline Right of Way at Edeoha. Picture was taken during Joint Investigation of 2<sup>nd</sup> July 2019.



Close-up: Illegal Fitting on 14" Okordia - Rumuekpe Pipeline at Edeoha. Picture was taken during Joint Investigation of 2<sup>nd</sup> July 2019.