



Overview: Part of spill impact on 24'' Nkpoku - Bomu Pipeline Right of Way at Sime. Picture was taken during Joint Investigation of 24th June 2019.



Close-up: Illegal Fitting on 24'' Nkpoku - Bomu Pipeline at Sime. Picture was taken during Joint Investigation of 24th June 2019.