


**Overview:** Part of spill impact on 12'' Imo River – Ogale Pipeline Right of Way at Uzuaku. Picture was taken during Joint Investigation of 12<sup>th</sup> March 2019.



**Close-up:** Leaking Illegal Fittings on 12'' Imo River – Ogale Pipeline at Uzuaku. Picture was taken during Joint Investigation of 12<sup>th</sup> March 2019