




**Overview:** Part of spill impact on 28" Bomu - Bonny Pipeline Right of Way at Owokiri. Picture was taken during Joint Investigation of 6<sup>th</sup> March 2019.



**Close-up:** Illegal Fitting on 28" Bomu - Bonny Pipeline at Owokiri. Picture was taken during Joint Investigation of 6<sup>th</sup> March 2019