




Overview: Part of spill impact on 36'' Nkpoku Bomu Pipeline Right of Way at Elenwo. Picture was taken during Joint Investigation of 21st March 2019.



Close-up: Tampered Clamp on 36'' Nkpoku Bomu Pipeline at Elenwo. Picture was taken during Joint Investigation of 21st March 2019