




**Overview:** Part of spill impact on 8'' Nkali - ImoRiver Pipeline Right of Way at Odagwa. Picture was taken during Joint Investigation of 25<sup>th</sup> March 2019.



**Close-up:** Sand bag on 8'' Nkali - ImoRiver Pipeline at Odagwa. Picture was taken during Joint Investigation of 25<sup>th</sup> March 2019



Close-up: Illegal Fitting on 8'' Nkali - ImoRiver Pipeline at Odagwa. Picture was taken during Joint Investigation of 25<sup>th</sup> March 2019