



**Overview:** Part of spill impact on 36'' Nkpoku - Bomu Pipeline Right of Way at Atali. Picture was taken during Joint Investigation of 26<sup>th</sup> March 2019.



**Close-up:** Leaking Illegal fitting on 36'' Nkpoku - Bomu Pipeline at Atali. Picture was taken during Joint Investigation of 27<sup>th</sup> March 2019