



**Overview:** Part of spill impact on 10'' Diebu Creek – Nun River Pipeline Right of Way at Peremabiri. Picture was taken during Joint Investigation of 28<sup>th</sup> March 2019.



**Close-up:** Crack on 10'' Diebu Creek – Nun River Pipeline at Peremabiri. Picture was taken during Joint Investigation of 28<sup>th</sup> March 2019