


Overview: Part of spill impact on 16'' Tunu - Brasscreek Pipeline Right of Way at Agbidiana. Picture was taken during Joint Investigation of 9th April 2019.



Close-up: Illegal fitting on 16'' Tunu - Brasscreek Pipeline at Agbidiana. Picture was taken during Joint Investigation of 9th April 2019