


**Overview:** Part of spill impact on 28" Nkpoku – Bomu Pipeline Right of Way at B-Dere. Picture was taken during Joint Investigation of 19<sup>th</sup> April 2019.



**Close-up:** Illegal fitting on 28" Nkpoku – Bomu Pipeline at B-Dere. Picture was taken during Joint Investigation of 19<sup>th</sup> April 2019