




Overview: Part of spill impact on 14" Okordia - Rumuekpe Pipeline Right of Way at Akala-Olu. Picture was taken during Joint Investigation of 7th May 2019.



Close-up: Illegal fitting on 14" Okordia - Rumuekpe Pipeline at Akala-Olu. Picture was taken during Joint Investigation of 7th May 2019