




Overview: Part of spill impact on 24" Bomu – Bonny Pipeline Right of Way at Patrick Waterside - Bodo West. Picture was taken during Joint Investigation of 6th March 2019.



Close-up: Illegal Fitting on 24" Bomu – Bonny Pipeline at Patrick Waterside – Bodo West. Picture was taken during Joint Investigation of 6th May 2019