


**Overview:** Part of spill impact on 28" Bomu – Bonny Pipeline Right of Way at Owokiri. Picture was taken during Joint Investigation of 14<sup>th</sup> May 2019.



**Close-up:** Hack Saw Cuts on 28" Bomu – Bonny Pipeline at Owokiri. Picture was taken during Joint Investigation of 14<sup>th</sup> May 2019