



Overview: Part of spill impact on Obigbo North Well 3L/S Flowlines at Umuebulu. Picture was taken during Joint Investigation of 16th May 2019.



Close-up: Illegal Fittings on Obigbo North Well 3L/S Flowlines at Umuebulu. Picture was taken during Joint Investigation of 16th May 2019