



Overview: Part of spill impact on 20" Kolocreek – Rumuekpe Pipeline Right of Way at Okoma-1. Picture was taken during initial site visit of 17<sup>th</sup> May 2019.



Close-up: Drilled Hole on 20" Kolocreek – Rumuekpe Pipeline at Okoma-1. Picture was taken during Joint Investigation of 18<sup>th</sup> May 2019.