




Overview: Part of spill impact on 20'' Kolocreek – Rumuekpe Pipeline Right of Way at Okoma-1. Picture was taken during Joint Investigation of 21st May 2019.



Close-up: Leaking Illegal Fitting on 20'' Kolocreek – Rumuekpe Pipeline at Okoma-1. Picture was taken during Joint Investigation of 21st May 2019.