



Overview: Part of spill impact on 20'' Kolocreek – Rumuekpe Pipeline Right of Way at Odau. Picture was taken during Joint Investigation of 21st May 2019.



Close-up: Illegal fittings on 20'' Kolocreek – Rumuekpe Pipeline at Odau. Picture was taken during Joint Investigation of 21st May 2019