




Overview: Part of spill impact on 16'' Egbema – Assa Pipeline Right of Way at Assa. Picture was taken during Joint Investigation of 23rd May 2019.



Close-up: Plugged leaking Illegal fitting on 16'' Egbema – Assa Pipeline at Assa. Picture was taken during Joint Investigation of 23rd May 2019