



Overview: Part of spill impact on 4" Opukushi Well 9T Flowline at Egbemo-Analabiri-agbidiana. Picture was taken during Joint Investigation of 7th May 2019.



Close-up: Missing part of the Flowline on 4" Opukushi Well 9T Flowline at Egbemo-Analabiri-agbidiana. Picture was taken during Joint Investigation of 7th May 2019.