



Overview: Part of spill impact on 12" Imo River - Ogale Pipeline Right of Way at Umuololo. Picture was taken during Joint Investigation of 29th May 2019.



Close-up: Illegal fitting on 12" Imo River - Ogale Pipeline at Umuololo. Picture was taken during Joint Investigation of 30th May 2019