



Overview: Part of spill impact on 4" Opukushi Well 24T Flowline at Egbemo Analabiri & Agbidiana. Picture was taken during Joint Investigation of 7th May 2019.



Close-up: Missing part of the Flowline on 4" Opukushi Well 24T Flowline at Egbemo Analabiri & Agbidiana. Picture was taken during Joint Investigation of 7th May 2019.