



Overview: Part of spill impact on Yokri LP1 bulkline manifold 8 at Yokiri. Picture was taken during Joint Investigation of 15th May 2019.



Close-up: Corrosion on Yokri LP1 bulk-line manifold 8 at Yokiri. Picture was taken during Joint Investigation of 15th May 2019