




Overview: Part of spill impact on 12'' Oguta – Egbema Pipeline Right of Way at Umunkwu. Picture was taken during Joint Investigation of 5th June 2019.



Close-up: Illegal fitting on 12'' Oguta – Egbema Pipeline at Umunkwu. Picture was taken during Joint Investigation of 5th June 2019