


Overview: Part of spill impact on 28" Bomu – Bonny Pipeline Right of Way at Owokiri. Picture was taken during Joint Investigation of 31st May 2019.



Close-up: Illegal Fitting on 28" Bomu – Bonny Pipeline at Owokiri. Picture was taken during Joint Investigation of 31st May 2019.