




Overview: Part of spill impact on 6" Opukushi Well 25T Flowline at Egbemo-Analabiri-Agbidiana. Picture was taken during Joint Investigation of 7th May 2019.



Close-up: Missing part of the Flowline on 6" Opukushi Well 25T Flowline at Egbemo-Analabiri-Agbidiana. Picture was taken during Joint Investigation of 7th May 2019