



Overview: Part of spill impact on 12" Imo River – Ogale Pipeline Right of Way at Igiriukwu-Owaza. Picture was taken during Joint Investigation of 1st June 2019.



Close-up: Corrosion on 12" Imo River – Ogale Pipeline at Igiriukwu-Owaza. Picture was taken during Joint Investigation of 2nd June 2019.