



Overview: Part of spill impact on 20" Otumara - escravos Pipeline Right of Way at Ugboegungun. Picture was taken during Joint Investigation of 10<sup>th</sup> May 2019.



Close-up: Illegal fitting on 20" Otumara - escravos Pipeline at Ugboegungun. Picture was taken during Joint Investigation of 10<sup>th</sup> May 2019.