



Overview: Part of spill impact on 20'' Trans - Escravos Pipeline Right of Way at Ugboegungun. Picture was taken during Joint Investigation of 4th November 2019.



Close-up: Illegal Fitting on 20'' Trans - Escravos Pipeline at Ugboegungun. Picture was taken during Joint Investigation of 4th November 2019.